




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout


Thursday, December 03, 2015 4:58 PM




0049_335_1357_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout


Thursday, December 03, 2015 4:59 PM




0050_335_1407_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0050_335_1407_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0050_335_1407_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0050_335_1407_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0050_335_1407_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0050_335_1407_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF


0m




0050_335_1407_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF


Printout

Thursday, December 03, 2015 4:59 PM




0051_335_1412_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF







0051_335_1412_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0051_335_1412_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0051_335_1412_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0051_335_1412_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout


Thursday, December 03, 2015 5:00 PM




0052_335_1417_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0052_335_1417_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0052_335_1417_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0052_335_1417_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0052_335_1417_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0052_335_1417_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0052_335_1417_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout


Thursday, December 03, 2015 5:00 PM



0053_335_1423_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0053_335_1423_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0053_335_1423_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF


0m




0053_335_1423_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout


Thursday, December 03, 2015 5:01 PM




0054_335_1426_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0054_335_1426_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0054_335_1426_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0054_335_1426_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0054_335_1426_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout


Thursday, December 03, 2015 5:01 PM




0055_335_1430_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0055_335_1430_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0055_335_1430_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0055_335_1430_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout


Thursday, December 03, 2015 5:02 PM




0056_335_1435_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0056_335_1435_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0056_335_1435_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0056_335_1435_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0056_335_1435_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout


Thursday, December 03, 2015 5:02 PM




0057_335_1439_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0057_335_1439_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0057_335_1439_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF




0057_335_1439_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0057_335_1439_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF


0m




0057_335_1439_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF

Printout

Friday, December 04, 2015 1:51 PM



0056_335_1434_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF



0056_335_1434_120274_CHP4.0_DET_000.sgy_prnt.job: 0 200 kHz HF